

ARCS PROCEDURE: Author: P. Malone	REBOOTING THE WSI COMPUTER	PRO(WSI)-017.001 September 28, 1999 Page 1 of 2
---	---------------------------------------	--

Rebooting the WSI Computer

I. Purpose:

Describes the procedure to reboot the WSI computer

II. Cautions and Hazards:

None.

III. Requirements:

None.

IV. Procedure:

A. Rebooting Procedure

1. Press 'X' on the keyboard (which shuts down the program and returns a DOS prompt).
2. Wait until you see the 'C:\runwsi' prompt (at this point the program can be restarted by typing "runwsi").
3. Check GPS (make sure display is on)
 - If not press the red button
4. If you see yellow or red flags, please check them. Please note them on the SDL report.

B. Alternative Rebooting Procedure

1. Press 'X' on the keyboard.
2. Wait until you see the 'C:\runwsi' prompt.
3. Turn the power key located in the middle of the black area under the monitor to the off position.
4. If you see yellow or red flags, please check them. Please note them on the SDL report.

V. References:

None.

VI. Attachments:

ARCS PROCEDURE: Author: P. Malone	REBOOTING THE WSI COMPUTER	PRO(WSI)-017.001 September 28, 1999 Page 2 of 2
--	---------------------------------------	--

None.