

ARCS PROCEDURE: Author: J. Zirzow	SKYRAD LOGGER POWER DIAGNOSTICS	PRO(DAQS)-006.000 May 11, 1999 Page 1 of 1
--	------------------------------------	--

SKYRAD Logger Power Diagnostics

I. Purpose:

To provide a procedure for checking the SKYRAD Logger power diagnostics.

II. Cautions and Hazards:

None.

III. Requirements:

None.

IV. Procedure:

A. Steps:

1. Find the two yellow surge protectors in a gray box outside the D-Van labeled SKYRAD.
2. Find some green wire in the U-van and make 4 wires-stripping both ends.
3. Jumper slots 1 to 3 and 2 to 4 on both SKYRAD surge protectors. You need to leave the current wires in place.

V. References:

None.

VI. Attachments:

None.